JVC

SERVICE MANUAL

COLOR TELEVISION

C-20110/x(US & CA)
AV-20120/x(US & CA)
AV-20121/x(US & CA)

BASIC CHASSIS

FV3

Supplementary


The following item for the A model were changed from those of the B model. Therefore, this service manual describes only the items which differ from those of the B service manual. For details other than those described in this manual, please refer to the B service manual (No.51693, Jan, 2000).

■ MODEL DIFFERENCE

B model
C-20110(US&CA)
AV-20120(US&CA), AV-20121(US&CA)

MODEL IDENTIFICATION

While referring to the illustration given below, identify model name on the rating label affixed to the rear cover.



■ DIFFERENCE PARTS LIST

EXPLODED VIEW PARTS LIST (Page26)

		Parts No	umber		
⚠	⚠ Ref. No.	C-20110(US&CA) (No.51693)	C-20110/x(US&CA) (No.51693B)	Parts Name	Remarks
\triangle	15	CM22998-001-A	CM22998-A01-A	RATING LABEL(US)	Not Interchangeable

• EXPLODED VIEW PARTS LIST (Page34)

		Parts No	Parts Number		
⚠	Ref. No.	AV-20120(US&CA) AV-20121(US&CA) (No.51693)	AV-20120/x(US&CA) AV-20121/x(US&CA) (No.51693B)	Parts Name	Remarks
⚠	15	CM22998-001-A	CM22998-A01-A	RATING LABEL(US)	Not Interchangeable

• MAIN PWB PARTS LIST (Page28~31)

	Ref. No.	Parts	Number		
Λ		C-20110(US&CA) (No.51693)	C-20110/X(US&CA) (No.51693B)	Parts Name	Remarks
		SFV-1028A-M2	SFV-1044A-M2	Main PWB	Not Interchangeable
	R1001	QRE121J-5R6Y		C RESISTER	Delete
	R1005	QRG01GJ-121		OM RESISTER	1
	R1146	NRSA02J-273X	NRSA02J-562X	CHIP RESISTER	Not Interchangeable
	C1006	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1013		NCB21HK-104X	CHIP C CAP.	Addition
	C1138	QETN1CM-476Z	QETN1EM-476Z	E CAP.	Not Interchangeable
	C1217	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1511	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1716	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1751	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1922	QEHB2CM-336	QEHQ2CM-336	E CAP.	1
	L1001	QQL03BJ-150Z		PEAKING COIL	Delete
	D1002	MTZJ5.1B-T2		CHIP ZENER	1
	IC1001		AN7805F	I.C.	Addition
	IC1701	M37272MA-050SP	M37272MA-053SP	I.C.	Not Interchangeable
⚠	TU1001	QAU0145-001	QAU0199-001	TUNER	1

MAIN PWB PARTS LIST (Page36~39)

	Ref. No.	Parts N	lumber		
⚠		AV-20120(US&CA) AV-20121(US&CA) (No.51693)	AV-20120/x(us&ca) AV-20121/x(us&ca) (No.51693B)	Parts Name	Remarks
		SFV-1029A-M2	SFV-1045A-M2	Main PWB (AV-20120/x)	Not Interchangeable
		SFV-1030A-M2	SFV-1046A-M2	Main PWB (AV-20121/x)	1
	R1001	QRE121J-5R6Y		C RESISTER	Delete
	R1005	QRG01GJ-121		OM RESISTER	1
	R1146	NRSA02J-273X	NRSA02J-562X	CHIP RESISTER	Not Interchangeable
	C1006	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1013		NCB21HK-104X	CHIP C CAP.	Addition
	C1138	QETN1CM-476Z	QETN1EM-476Z	E CAP.	Not Interchangeable
	C1217	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1

2 No. 51693B


• MAIN PWB PARTS LIST (Page36~39)


	Ref. No.	Parts Number			
Δ		AV-20120(US&CA) AV-20121(US&CA) (No.51693)	AV-20120/x(us&ca) AV-20121/x(us&ca) (No.51693B)	Parts Name	Remarks
		SFV-1029A-M2	SFV-1045A-M2	Main PWB (AV-20120/x)	Not Interchangeable
		SFV-1030A-M2	SFV-1046A-M2	Main PWB (AV-20121/x)	1
	C1511	QETN1CM-476Z	QETN1EM-476Z	E CAP.	Not Interchangeable
	C1617	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1623	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1680	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1716	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1751	QETN1CM-476Z	QETN1EM-476Z	E CAP.	1
	C1922	QEHB2CM-336	QEHQ2CM-336	E CAP.	1
	L1001	QQL03BJ-150Z		PEAKING COIL	Delete
	D1002	MTZJ5.1B-T2		CHIP ZENER	1
	IC1001		AN7805F	I.C.	Addition
	IC1701	M37272MA-050SP	M37272MA-053SP	I.C.	Not Interchangeable
⚠	TU1001	QAU0069-001	QAU0199-001	TUNER	↑

• PACKING

	⚠ Ref. No.	Parts Number			
◮		C-20120(us&ca) AV-20120(us&ca) AV-20121(us&ca) (No.51693)	C-20120/x(US&CA) AV-20120/x(US&CA) AV-20121/x(US&CA) (No.51693B)	Parts Name	Remarks
⚠	6	LCT0606-001A-A	LCT0606-001B-A	INST BOOK (CA) [FRENCH]	Not Interchangeable (Page 33&41)

Changed around the Tuner(Page 2-7,2-9)





No. 51693B 3

JVC SERVICE & ENGINEERING COMPANY OF AMERICA

DIVISION OF JVC AMERICAS CORP.

Head office :	1700 Valley Road, Wayne, New Jersey 07470	(973)315-5000
East Coast:	10 New Maple Avenue, Pine Brook, New Jersey 07058	(973)396-1000
Midwest :	705 Enterprise St. Aurora, Illinois 60504	(630)851-7855
West Coast:	5665 Corporate Avenue, Cypress, California 90630	(714)229-8011
Southwest:	10700 Hammerly, Suite 105, Houston, Texas 77043	(713)935-9331
Hawaii :	2969 Mapunapuna Place, Honolulu, Hawaii 96819	(808)833-5828
Southeast :	1500 Lakes Parkway, Lawrenceville, Georgia 30243	(770)339-2582

JVC CANADA INC.

Head office: 21 Finchdene Square Scarborough, Ontario M1X 1A7 (416)293-1311 **Vancouver**: 13040 Worster Court Richmond B.C. V6V 2B3 (604)270-1311

